




Remove
Grommet
& Outlet
(No Electric)

Add Storage

(As much as possible on Cold)

Move Storage
and Cash Drawer to
Operator Side

Cash Drawer on Operator
Left of Unit